



Burlington WA Corporate Office 1620 S Walnut St - 98233 800.755.9295 • 360.757.1400
 Bellingham WA Microbiology 805 Orchard Dr Ste 4 - 98225 360.671.0688
 Portland OR Microbiology/Chemistry 9150 SW Pioneer Ct Ste W- 97070 503.682.7802



INORGANIC COMPOUNDS (IOC) REPORT

Client Name: Beverly Beach Improvement Club
 PO BOX 12
 Freeland, WA 98249

Reference Number: 11-05841
 Project: Chloride/E. Conductivity

System Name: BEVERLY BEACH IMP. CLUB
 System ID Number: 061475
 DOH Source Number: 02
 Multiple Sources:
 Sample Type: A - After treatment
 Sample Purpose: C - Compliance
 Sample Location: Well Pumphouse
 County: Island

Sample Number: Beverly Beach Imp.
 Lab Number: 046-12856
 Collect Date: 4/21/11 11:45
 Date Received: 4/21/11
 Report Date: 4/26/11
 Sampled By: S. Wicklund
 Sampler Phone: 360-730-1354
 Released by: *SW*

DOH#	ANALYTES	RESULTS	UNITS	SRL	Trigger	MCL	Analyst	METHOD	Analyzed	COMMENT
16	Other ELECTRICAL CONDUCTIVITY	378	uS/cm	10		700	srf	SM2510 B	04/25/11	
21	EPA Regulated (Secondary) CHLORIDE	20	mg/L	0.1		250	bj	300.0	04/22/11	

NOTES:

SRL (State Reporting Level): indicates the minimum reporting level required by the Washington Department of Health (DOH).
 MCL (Maximum Contaminant Level) maximum permissible level of a contaminant in water established by EPA; Federal Action Levels are 0.015 mg/L for Lead and 1.3 mg/L for Copper. Sodium has a recommended limit of 20 mg/L. A blank MCL value indicates a level is not currently established.
 Trigger Level: DOH Drinking Water Response level. Systems with compounds detected in excess of this level are required to take additional samples. Contact your regional DOH office.
 ND (Not Detected): indicates that the parameter was not detected above the Specified Reporting Limit (SRL).
 An * in front of the parameter name indicates it is not NELAP accredited but it is accredited through WSDOH or USEPA Region 10.

These test results meet all the requirements of NELAC, unless otherwise stated in writing, and relate only to these samples.
 If you have any questions concerning this report contact us at the above phone number.