



Burlington WA  
Corporate Office

1620 S Walnut St - 98233  
800.755.9295 • 360.757.1400

Bellingham WA  
Microbiology

805 Orchard Dr Ste 4 - 98225  
360.671.0688

Portland OR  
Microbiology/Chemistry

9150 SW Pioneer Ct Ste W- 97070  
503.682.7802

## INORGANIC COMPOUNDS (IOC) REPORT

Client Name: Beverly Beach Improvement Club  
PO BOX 12  
Freeland, WA 98249

Reference Number: 13-08506  
Project: Asbestos

System Name: BEVERLY BEACH IMPROVEMENT CLUB  
System ID Number: 061475  
DOH Source Number: 02  
Multiple Sources:  
Sample Type: B - Before treatment  
Sample Purpose: C - Compliance  
Sample Location: Well Head  
County: Island

Sample Number: Asbestos  
Lab Number: 119-19645  
Collect Date: 5/16/13 08:00  
Date Received: 5/16/13  
Report Date: 5/29/13  
Sampled By: Joe Waldrup  
Sampler Phone: 360-675-2457  
Released by:

DOH#	ANALYTES	RESULTS	UNITS	SRL	Trigger	MCL	Analyst	METHOD	Analyzed	COMMENT
0	ASBESTOS	ND	MFL>10um	4.9		7	tysh	100.2	05/29/13	Analyzed by EMSL

**NOTES:**

SRL (State Reporting Level): indicates the minimum reporting level required by the Washington Department of Health (DOH).

MCL (Maximum Contaminant Level) maximum permissible level of a contaminant in water established by EPA; Federal Action Levels are 0.015 mg/L for Lead and 1.3 mg/L for Copper. Sodium has a recommended limit of 20 mg/L. A blank MCL value indicates a level is not currently established.

Trigger Level: DOH Drinking Water Response level. Systems with compounds detected in excess of this level are required to take additional samples. Contact your regional DOH office.

ND (Not Detected): indicates that the parameter was not detected above the Specified Reporting Limit (SRL).

If you have any questions concerning this report contact us at the above phone number.